CUSTOMER ADVISORY

Advisory for Customers using the Single-Event Upset (SEU) detection feature on the Titanium Ti60 & Ti35

Advisory details	Customers who want to use the Single-Event Upset (SEU) detection feature on the Titanium Ti60 & Ti35 must use parts assembled with date code later than "2211". For customers who want to use the Single-Event Upset (SEU) detection feature on the Ti60F225 dev board, customer needs to use the "Rev. A2" dev board.
Parts Affected	All Ti60 & Ti35 parts and variants • Ti60F225XX • Ti35F225XX • Ti60F100S3F2XX • Ti35F100S3F2XX • Ti60F225-DK XX = All speed grades
Contact:	For more information, please contact your local Sales or FAE or contact us online at https://efinixinc.com/company-contact-us.html .